

L Numb r	Hits	S arch T xt	DB	Tim stamp
51	549	driver n ar11 (disabl\$3 inhibit\$3 int rrupt\$3 prev nt\$3) near11 (fac\$3 visi n visual s e watch\$3)	USPAT	2003/10/02 17:19
52	21	(driv r n ar11 (disabl\$3 inhibit\$3 interrupt\$3 prevent\$3) near11 (fac\$3 vision visual see watch\$3)) near11 (accident crash distract\$3)	USPAT	2003/10/02 16:34
53	580	driver near11 (disabl\$3 inhibit\$3 interrupt\$3 prevent\$3) near11 (fac\$3 vision visual see watch\$3 visible)	USPAT	2003/10/02 17:20
92	17171	(moving movable rotating rotatable) near5 (display monitor)	USPAT	2003/10/02 18:12
93	416	(driving driver) near11 ((moving movable rotating rotatable) near5 (display monitor))	USPAT	2003/10/02 17:22
94	66	((driving driver) near11 ((moving movable rotating rotatable) near5 (display monitor))) same (vehicle car automobile)	USPAT	2003/10/02 17:23
95	18	("4679158" "4854538" "4908611" "4962998" "5027104" "5056905" "5059956" "5289321" "5306953" "5530421" "5668675" "5670935" "5684647" "5708857" "5719713" "5745310" "5793308" "5823599").PN.	USPAT	2003/10/02 17:43
96	3	6304173.URPN.	USPAT	2003/10/02 17:46
97	11	("4908611" "5260729" "5369581" "5428355" "5534888" "5555502" "5582518" "5757268" "5867133" "5871251" "5873621").PN.	USPAT	2003/10/02 17:46
98	2	6067078.URPN.	USPAT	2003/10/02 17:52
99	3	5734358.URPN.	USPAT	2003/10/02 17:53
100	8	("3603667" "4623223" "4635033" "4711544" "4723160" "4908611" "4925272" "5032828").PN.	USPAT	2003/10/02 17:53
101	1210	((348/118) or (345/156)).CCLS.	USPAT	2003/10/02 18:00
102	217	((moving movable rotating rotatable) near5 (display monitor)) and (((348/118) or (345/156)).CCLS.)	USPAT	2003/10/02 18:02
103	44	((moving movable rotating rotatable) near5 (display monitor)) and (((348/118) or (345/156)).CCLS.)) and (car automobile vehicle)	USPAT	2003/10/02 18:03
104	348	(display monitor) near11 panel near11 (first) n ar11 se nd n ar11 position	USPAT	2003/10/02 18:15
105	92	(display m nitor) near11 (driver driving) n ar11 (first) near11 s c nd n ar11 p sition	USPAT	2003/10/02 18:17
106	47	(pass nger) n ar11 (driv r driving) n ar11 (first) n ar11 s c nd n ar11 p siti n	USPAT	2003/10/02 18:22

107	33	(pass ng r n ar11 (driv r driving)) sam (first n ar11 s c nd n ar11 p sition) sam (display monitor tv t levisi n panel)	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/10/02 18:44
108	0	20020175564.URPN.	USPAT	2003/10/02 18:32
109	371	(passenger near11 driver) same (position near11 (display monitor tv television panel))	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/10/02 19:33
110	50	(NAUMANN near FRITZ).inv.	USPAT; US-PGPUB; EPO; JPO; DERWENT; IBM_TDB	2003/10/02 19:57
111	9	4213129.URPN.	USPAT	2003/10/02 19:35
112	300	(296/70).CCLS.	USPAT	2003/10/02 19:58
113	63	(dash dashboard) near11 (panel monitor display) near11 (rotate roatting swivel movable)	USPAT	2003/10/02 20:02
114	15	((instrument adj panel) dashboard) near11 (monitor display) near11 (rotate roatting swivel movable)	USPAT	2003/10/02 20:04
115	498	((instrument adj panel) dashboard) near11 (monitor display) near11 (passenger driver)	USPAT	2003/10/02 21:55
116	8	("4225005" "4521078" "4724918" "4983951" "5288558" "5457575" "5687944" "5873557").PN.	USPAT	2003/10/02 20:16
117	0	6448893.URPN.	USPAT	2003/10/02 20:17
118	98	(disabl\$3 inhibit\$3 prohibit\$3) near11 (control input switch button key) near11 driver near11 (monitor display)	USPAT	2003/10/02 22:03
119	13	6202008.URPN.	USPAT	2003/10/02 21:59
120	25	("4068175" "4207511" "4365280" "4477764" "4481512" "4497038" "4868715" "4895326" "4911386" "5060229" "5104071" "5143343" "5198696" "5316868" "5424709" "5488283" "5569997" "5610376" "5641953" "5797164" "5918183" "5922040" "5949345" "6009363" "6032084").PN.	USPAT	2003/10/02 22:00
121	11	(disabl\$3 inhibit\$3 pr hibit\$3) near11 (radio vid movie nt rtainm nt cd music dvd) near11 driv r near11 (monitor display)	USPAT	2003/10/02 22:09
122	1	"5815093".PN.	USPAT	2003/10/02 22:08

123	1	6144296.URPN.	USPAT	2003/10/02 22:08
124	87	(disabl\$3 inhibit\$3 prohibit\$3) near11 (radio vid o movi entertainm nt cd music dvd) n ar11 (p ration functi n) n ar11 (monitor display)	USPAT	2003/10/02 22:20
125	1733	(307/10.1).CCLS.	USPAT	2003/10/02 22:17
126	11853	(disabl\$3 inhibit\$3 prohibit\$3) near11 (monitor display)	USPAT	2003/10/02 22:21
127	14	((307/10.1).CCLS.) and ((disabl\$3 inhibit\$3 prohibit\$3) near11 (monitor display))	USPAT	2003/10/02 22:20
128	5712	(disabl\$3 inhibit\$3 prohibit\$3) near11 (radio video movie entertainment cd music dvd)	USPAT	2003/10/02 22:20
129	0	((307/10.1).CCLS.) and (4999783.PN. and (("3845289" "4570227" "4608656" "4611293" "4672565" "4673878" "4723218" "4734863" "4751512" "4782447" "4796191" "4797841" "4831563" "4862398" "4914605" "4918609" "4926336" "4937753" "4964052" "4970652" "4982332" "4984168" "4989151" "4992947" "4996645" "4999783" "5040122" "5046011" "5060162" "5177685" "5283743" "5287297" "5297050" "5471389" "5510983" "5764139" "5794164").PN.))	USPAT	2003/10/02 22:20
130	3	((307/10.1).CCLS.) and ((disabl\$3 inhibit\$3 prohibit\$3) near11 (radio video movie entertainment cd music dvd))	USPAT	2003/10/02 22:20
131	20	(monitor display) near11 driver near11 (visual vision) near11 (disabl\$3 inhibit\$3 interrupt\$3 prevent\$3)	USPAT	2003/10/02 22:46
132	32	5404443.URPN.	USPAT	2003/10/02 22:23
133	1	("6181996").PN.	USPAT	2003/10/02 22:46
134	9	("5748748" "5781437" "5839086" "5871232" "5938719" "6016110" "6023290" "6029110" "6059843").PN.	USPAT	2003/10/02 22:42
135	535	(701/36).CCLS.	USPAT	2003/10/02 22:46
136	35495	(monitor display) near11 (disabl\$3 inhibit\$3 interrupt\$3 prevent\$3)	USPAT	2003/10/02 22:46
137	31	((701/36).CCLS.) and ((monitor display) near11 (disabl\$3 inhibit\$3 interrupt\$3 prevent\$3))	USPAT	2003/10/02 22:47